

WORKSHOP MANUAL ZERO TURN MOWER

ZD18(F) ·ZD21(F) ZD28(F)

Kyboła

TO THE READER

This Workshop Manual has been prepared to provide servicing personnel with information on the mechanism, service and maintenance of ZD18(F), ZD21(F) and ZD28(F) KUBOTA ZD Series ZERO-TURN MOWER. It is divided into two parts, "Mechanism" and "Servicing" for each section.

Mechanism

Information on the Features and New Mechanisms are described. This information should be understood before proceeding with troubleshooting, disassembling and servicing.

Servicing

The heading "General" includes general precautions, check and maintenance and special tools. Other section, there are troubleshooting, checking and adjusting, disassembling and assembling, and servicing which cover procedures, precautions, factory specifications and allowable limits.

All information illustrations and specifications contained in this manual are based on the latest product information available at the time of publication. The right is reserved to make changes in all information at any time without notice.

March 2002

© KUBOTA Corporation 2002