




WALK-BEHIND ROLLER

SERVICE MANUAL SM31001

February 2000

Model 70B



DIN EN ISO 9001
Certificate No. 59557-01

CALIFORNIA

Proposition 65 Warning

Diesel engine exhaust and some of its constituents are known
to the State of California to cause cancer, birth defects, and
other reproductive harm.

table of contents

SECTION ONE

GENERAL	1 - 1
MACHINE DESCRIPTION	1 - 4
MODEL 70B DIMENSIONAL DATA	1 - 7
FLUID CAPACITIES	1 - 7
MODEL 70B OPERATING DATA	1 - 8
ENGINE	1 - 8
WEIGHTS	1 - 8
TRAVEL SPEED	1 - 8
VIBRATION SYSTEM	1 - 8
STANDARD TORQUE DATA	1 - 9
METRIC/USA CONVERSIONS	1 - 10
DIESEL FUEL SPECIFICATION	1 - 11
ENGINE OIL SPECIFICATION	1 - 12
VIBRATORY SYSTEM OIL	1 - 13
DRIVE GEARS LUBRICATION	1 - 13
HYDRAULIC SYSTEM OIL	1 - 13
MACHINE STORAGE	1 - 14
SAFETY	1 - 15
SPARK ARRESTER	1 - 15
PERSONAL	1 - 15
MACHINE OPERATION	1 - 16
MAINTENANCE	1 - 17

SECTION TWO

ENGINE	2 - 1
ENGINE SPECS.	2 - 2
RUN-IN PERIOD	2 - 2
DIESEL FUEL SPECIFICATION	2 - 3
ENGINE OIL SPECIFICATION	2 - 4

SECTION THREE

ELECTRICAL	3 - 1
ENGINE ELECTRICAL	3 - 2
UNDERSTANDING STARTERS	3 - 2
STARTER SOLENOID	3 - 3
70B STARTING CIRCUIT FUNCTION	3 - 4
ELECTRICAL SCHEMATIC 70B	3 - 5

SECTION FOUR

HYDRAULIC	4 - 1
70B HYDRAULIC SYSTEM	4 - 2
HYDRAULIC DESCRIPTION	4 - 4
CHARGE RELIEF	4 - 6
VIBRATION VALVE	4 - 6
HYDRAULIC PRESSURE TEST	4 - 8

SECTION FIVE

FINAL DRIVE	5 - 1
LOWER DRIVE UNIT	5 - 2
LOWER UNIT ASSEMBLY	5 - 6

SECTION SIX

VIBRATION SYSTEM	6 - 1
VIBRATION SYSTEM	6 - 2
VIBRATION FREQUENCY & AMPLITUDE	6 - 3
VIBRATORY SYSTEM DIAGNOSTICS	6 - 4
VIBRATION VALVE	6 - 5
VIBRATORY SHAFT.....	6 - 7

SECTION SEVEN

DRIVE CONTROLS	7 - 1
GUIDE BAR	7 - 2
DRIVE CONTROL & CABLE	7 - 3
DRIVE CABLE RETURN MECHANISM	7 - 10